

Detail No.: 5.09 DS

**Date: October 2014** 

## StoPowerwall® DrainScreen™ Joint, Rough Opening, and Transition Detail Treatments

Notes: Wood Frame 1. Joint treatment options: Sheathing Joint a. Sto Gold Fill with StoGuard® Mesh b. StoGuard® Fabric embedded in StoGuard® Waterproof Air Sto joint treatment Barrier Membrane c. StoGuard® RapidFill™ StoGuard® d. StoGuard<sup>®</sup> RapidSeal<sup>™</sup> with Waterproof Air StoGuard® Mesh Barrier Membrane 2. Rough Opening treatment Code Compliant options: Water-Resistive a. Sto Gold Fill with Barrier StoGuard® Mesh b. StoGuard® Fabric embedded Sto DrainScreen™ in StoGuard® Waterproof Air Barrier Membrane c. StoGuard® RapidSeal™ with StoGuard® Mesh 3. Sto Detail Component options: a. Sto Gold Fill with StoGuard® Mesh b. StoGuard® Fabric embedded in StoGuard® Waterproof Air Barrier Membrane c. StoGuard<sup>®</sup> RapidSeal<sup>™</sup> d. StoGuard<sup>®</sup> RapidFill<sup>™</sup> Sto Rough Opening Treatment 4. StoGuard® Waterproof Air Barrier Membrane options: Sto Detail Component a. Sto EmeraldCoat® (high perm) Flashing b. StoGuard®VaporSeal™ (vapor impermeable) 5. Refer to product bulletins for application information on joint treatments. IMPORTANT: Components not identified as Sto are furnished by other manufactur-ers and are not necessarily installed by trades who install the Sto products. Refe to project specific contract documents.

www.stocorp.com **ATTENTION** 

Sto products are intended for use by qualified professional contractors, not consumers, as a component of a larger construction assembly as specified by a qualified design professional, general contractor or builder. They should be installed in accordance with those specifications and Sto's instructions. Sto Corp. disclaims all, and assumes no, liability for on-site inspections, for its products applied improperly, or by unqualified persons or entities, or as part of an improperly designed or constructed building, for the nonperformance of adjacent building components or assemblies, of for other construction activities beyond Sto's control. Improper use of Sto products or use as part of an improperly designed or constructed larger assembly or building may result in serious damage to Sto products, and to the structure of the building or its components

Property of Sto Corp. All Rights Reserved.